




HAZARD AND CARGO SYMBOLS

- Dangerous goods safety marks used for hazard identification of materials and vehicles during transportation.
- Vehicles carrying dangerous goods have to be fitted with orange signs



Class 1 Explosives



Class 2 Gases



Class 3 Flammable liquids



Class 4 Other Flammables



Class 5 Oxidizers



Class 6 Poisons






Class 7 Radioactive

Class 8 Corrosive



Class 9 Miscellaneous





Toxic



Very toxic



Harmful



Irritant



Highly flammable



Extremely flammable



Explosive



Dangerous to the environment







Oxidising



Corrosive


Cargo symbols

Sling here	 A vertical chain of three links, representing a sling.
Use no hooks	 A hook symbol with a large 'X' over it, indicating that hooks should not be used.
Temperature limitations	 A thermometer symbol with a diagonal line through it, indicating temperature restrictions.
Do not use forklift truck here	 A forklift truck symbol with a large 'X' over it, indicating that forklifts should not be used in this area.


Keep dry packing



Do not use blades



**Keep away from heat
Solar radiation**







Centre of gravity



**Handle with care
Do not drop**





Do not clamp	
Do not roll	
Perishable cargo	
Top	
Stacking limitation	