




LED厂的生产设备 LED factory

how to make the bulb

1step, welding (第一步:焊线)







2step, push the aluminum board on the body



The Third step, make the glue on the board



The Forth Step, connect the board with cable



The Fifth Step, put on the cover



The Sixth Step, put on the holder



The seven Step. 3in1machine 1500pcs/H









The Eighth Step, testing







Λ

Portable detection instrument:1300RMB



This instrument can check the power factory, wattagge, vottage.